



Fish Bath Thermometer White

Product Images



Designed to test the safety of your bath water.

The floating fish baby bath thermometer will float in the bath and display the current temperature of the water, with a perfect temperature indication point of 36°C.

- Temperature Range: 10°C to 50°C
- Image icon shows correct temperature for your baby's bath
- Measurement: °C
- Dimensions: H 145 x W 60mm
- Warranty: 1 year
- Manufacturer: TFA

Description

Designed to test the safety of your bath water.

The floating fish baby bath thermometer will float in the bath and display the current temperature of the water, with a perfect temperature indication point of 36°C.

- Temperature Range: 10°C to 50°C
- Image icon shows correct temperature for your baby's bath
- Measurement: °C
- Dimensions: H 145 x W 60mm
- Warranty: 1 year
- Manufacturer: TFA

Additional Information

Brand	TFA Dostmann
Humidity	no
Temperature	yes
Temperature Sensor	no
Hair Hygrometer	no
HACCP Compliant	no
Auto Switch Off	no
Hold Function	no
Probe Type	no
Warranty	1 Year
Calendar	no
Min/Max Readings	no
Humidity Sensor	no
Clip-On	no
Humidity Range	no
Weatherproof	no
Waterproof	yes
Solar Light	no
Probe Temperature	no
Temperature Resolution	+/- 1°C
Calibration	Can Not Be Calibrated
Dew Point	no
Comfort Level Indicator	yes
Size : Depth	1.5cm
Outdoor Temperature	no
Moon Phase	no

Backlight	no
Humidity Accuracy	no
Humidity Resolution	no
Indoor Humidity	no
Clock	no
Transmission Range	no
Transmission Frequency	no
Temperature Range	-15 to 50°C
Temperature Accuracy	+/- 1°C
Size : Height	14.5cm
Size : Width	6cm
Size : Width Measuring Units	6cm °C
Measuring Units	°C
Measuring Units PC Connection	°C no
Measuring Units PC Connection Touch Screen	°C no no
Measuring Units PC Connection Touch Screen Min/Max Reset	°C no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point Alarm	°C no no no no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity Alarm	°C no no no no no no no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity AlarmHigh/Low Temp Alarm	°C no no