



# **Decorative Outdoor Thermometer 38.5cm**

## **Product Images**



#### **Short Description**

Forged iron leaf style outdoor garden thermometer, finished in silver/black with large clear numbers and an aged feel to it.

Perfect for situating in your garden with a good range of temperature and supplied with fixing screws.

Mercury free and is suitable for indoor and outdoor use.

#### Description

Forged iron leaf style outdoor garden thermometer, finished in silver/black with large clear numbers and an aged feel to it.

Perfect for situating in your garden with a good range of temperature and supplied with fixing screws.

Mercury free and is suitable for indoor and outdoor use.

- Temperature Range: -30 °C to +50 °C
- Measurement: °C
- Dimensions: H 385 x W 148mm
- Warranty: 1 Year
- Manufacturer: TFA

## **Additional Information**

Brand	TFA Dostmann
Humidity	no
Temperature	
	yes
Temperature Sensor	no
Hair Hygrometer	no
HACCP Compliant	no
Auto Switch Off	no
Hold Function	no
Probe Type	no
Warranty	1 Year
Calendar	no
Min/Max Readings	no
Humidity Sensor	no
Clip-On	no
Humidity Range	no
Weatherproof	yes
Waterproof	no
Solar Light	no
Probe Temperature	no
Temperature Resolution	+/- 1°C
Calibration	Can Not Be Calibrated
Dew Point	no
Comfort Level Indicator	no
Size : Depth	3.5cm
Outdoor Temperature	yes
Moon Phase	no

Backlight	20
	no
Humidity Accuracy	no
Humidity Resolution	no
Indoor Humidity	no
Clock	no
Transmission Range	no
Transmission Frequency	no
Temperature Range	-30 to 50°C
Temperature Accuracy	+/- 1°C
Size : Height	38.5cm
Size : Width	14.8cm
Size : Width Measuring Units	14.8cm °C
Measuring Units	°C
Measuring Units PC Connection	°C no
Measuring Units PC Connection Touch Screen	°C no no
Measuring Units PC Connection Touch Screen Min/Max Reset	°C   no   no   no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point Alarm	°C     no     no     no     no     no     no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity Alarm	°C     no     no     no     no     no     no     no
Measuring UnitsPC ConnectionTouch ScreenMin/Max ResetDew Point AlarmHigh/Low Humidity AlarmHigh/Low Temp Alarm	°C     no     no